

Sets, Kits, and Outfits, Measuring Tool Set, Machinists: Set No. 6

SC: 5280-95-A01
NSN: 5280-00-278-9919
LIN: M20190

System Description

33 component parts, carried in one portable tool box, 72 lbs. Shares similar components with the Machinists Tool Set, NSN 5280-00-511-1950, LIN W44512.

System Mission

Provides necessary components to purge fire control instruments at organization, direct and general support maintenance levels.

This system is not currently in reset.

Reset Type

Reset Work (Field Level) - Work performed to correct equipment faults that are performed at the ORG/DS level; performed by unit level soldiers, augmented by contractor as required.

Reset Strategy

n/a

Reset Procedures

- Replace worn, broken, missing components IAW supply catalog.
- Reorder consumables IAW SC.

Reset Responsibility

Unit

Reset Location

This system is not currently in reset.

- Contact Information -

877.4.PMSKOT (877.476.7568)
rock-pm-skot@conus.army.mil